

APPENDIX A

Photographs of Water Quality Monitoring Stations



Photo 1. Quartz Creek flowing near Station RC-01, 03/02/05



Photo 2. Rock Creek stream channel near Station RC-02, 11/18/04



Photo 3. Rock Creek stream channel near Station RC-03, 03/02/05



Photo 4. Rock Creek stream channel near Stations RC-04 and RC-05, 11/18/04



Photo 5. Rock Creek stream channel near Station RC-06, 11/17/04



Photo 6. Squaw Creek stream channel near Station RC-07, 11/17/04 (Inset: Adult steelhead spawning at RC-07, 02/19/04. Photo by Greg Fahlenkamp, EKCD)



Photo 7. Rock Creek stream channel near Station RC-08, 11/17/04



Photo 8. Rock Creek stream channel near Station RC-09, 11/17/04



Photo 9. Rock Creek stream channel near Station RC-10, 3/1/05



Photo 10. Luna Gulch stream channel near Station LG-01, 11/17/04



Photo 11. Luna Gulch stream channel near Station LG-02, 3/1/05



Photo 12. Luna Gulch stream channel near Station LG-03, 3/1/05